



















WinCore® WINDING CORES—HANDLING INSTRUCTIONS

WINDING		
		
+	+	-
CLAMPING (We recommend clamping on hard rubber)		
		
+	+	
		
+	+	+
		-

WinCore® WINDING CORES—HANDLING INSTRUCTIONS

HANDLING AND STORAGE			
		+++	
		+++	
		+	
		+	
		-	